

PRODUCT CHANGE NOTIFICATION

PCN#: DUCT AND ABRASION 20180924-1

ISSUE DATE: _____

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Not Required for discontinuation)

Summary

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2019	1	1

***Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product continuation date.

IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)
HST0.4-3-Q2Y	HST0.4-6-X2Y
HST0.4-6-3Y	HST0.4-6-XY
HST0.8-12-5-2Y	HST0.8-48-5-2Y
HST0.8-6-3Y	HST0.8-6-XY
HST0.8-6-X2Y	HST0.8-9-X2Y
HST0.8-9-XY	HST0.8-12-5Y
HST1.1-12-5-2Y	HST1.1-48-5-2Y
HST1.1-6-3Y	HST1.1-6-XY
HST1.1-6-X2Y	HST1.1-9-X2Y
HST1.1-9-2Y	HST1.1-9-XY
HST1.5-12-1Y	HST1.5-12-5Y
HST2.0-9-5Y	HST2.0-12-2Y
HST2.7-12-2Y	HST2.7-48-2Y
HST3.0-12-2	HST3.0-48-2
HST3.5-12-2Y	HST3.5-48-2Y
HSTT05-M4	HSTT05-48-Q4
HSTT05-M6	HSTT05-48-Q6
HSTT05-MC	HSTT05-CC
HSTT05-QC	HSTT05-CC
HSTT06-48-TL	HSTT06-48-Q
HSTT06-M10	HSTT06-C10
HSTT06-M4	HSTT06-C4
HSTT06-M5	HSTT06-C5
HSTT06-MC	HSTT06-CC
HSTT06-QC	HSTT06-CC
HSTT09-48-TL	HSTT09-48-Q
HSTT09-M10	HSTT09-C10
HSTT09-M2	HSTT09-48-Q2
HSTT09-M4	HSTT09-48-Q4
HSTT09-M5	HSTT09-C5
HSTT09-M6	HSTT09-48-Q6
HSTT09-MC	HSTT09-CC
HSTT09-QC	HSTT09-CC
HSTT100-48-LQ	HSTT100-48-5
HSTT12-48-TL	HSTT12-48-Q
HSTT12-M10	HSTT12-C10
HSTT12-M2	HSTT12-C2
HSTT12-M4	HSTT12-C4
HSTT12-M45	HSTT12-48-Q45
HSTT12-M5	HSTT12-C5
HSTT12-M6	HSTT12-C6
HSTT12-MC	HSTT12-CC
HSTT12-Q45	HSTT12-48-Q45
HSTT12-QC	HSTT12-CC
HSTT19-M10	HSTT19-C10
HSTT19-M2	HSTT19-C2

HSTT19-M4	HSTT19-C4
HSTT19-M5	HSTT19-C5
HSTT19-M6	HSTT19-C6
HSTT19-MC	HSTT19-CC
HSTT19-Q45	HSTT19-48-Q45
HSTT19-QC	HSTT19-CC
HSTT200-L10	HSTT200-48-5-10
HSTT200-L2	HSTT200-48-5-2
HSTT200-L6	HSTT200-48-5-6
HSTT200-LC	HSTT200-48-5C
HSTT25-48-TL	HSTT25-48-Q
HSTT25-D10	HSTT25-C10
HSTT25-D2	HSTT25-C2
HSTT25-D4	HSTT25-C4
HSTT25-D45	HSTT25-48-Q45
HSTT25-D5	HSTT25-C5
HSTT25-D6	HSTT25-C6
HSTT25-DC	HSTT25-CC
HSTT25-Q45	HSTT25-48-Q45
HSTT25-QC	HSTT25-CC
HSTT25-YC	HSTT25-CC
HSTT38-48-TL	HSTT38-48-Q
HSTT38-Q45	HSTT38-48-Q45
HSTT38-QC	HSTT38-CC
HSTT50-48-T	HSTT50-48-Q
HSTT50-Q45	HSTT50-48-545
HSTT50-QC	HSTT50-CC
HSTT75-48-CQ	HSTT75-48-5
HSTT75-Q45	HSTT75-48-545
HSTT75-QC	HSTT75-CC
HSTTN100-CY	No Replacement
HSTTN125-CY	No Replacement
HSTTN150-CY	No Replacement
HSTTN175-CY	No Replacement
HSTTN200-QY	No Replacement
HSTTN25-CY	No Replacement
HSTTN38-CY	No Replacement
HSTTN50-CY	No Replacement
HSTTN63-CY	No Replacement
HSTTN75-CY	No Replacement
HSTTN88-CY	No Replacement
HSTTP05-CY	No Replacement
HSTTP05-QY	No Replacement
HSTTP12-MY	HSTTP12-CY
HSTTP19-MY	HSTTP19-CY
HSTTP25-DY	HSTTP25-CY
HSTTP38-TY	HSTTP38-CY

HSTTV05-M2	No Replacement
HSTTV05-Q	HSTTV05-C
HSTTV06-Q	HSTTV06-C
HSTTV09-Q	HSTTV09-C
HSTTV100-48-LQ	HSTTV100-48-5
HSTTV100-Q	HSTTV100-C
HSTTV12-48-TL	HSTTV12-48-Q
HSTTV12-M2	No Replacement
HSTTV12-M6	No Replacement
HSTTV19-48-TL	HSTTV19-48-Q
HSTTV19-M2	No Replacement
HSTTV19-M4	No Replacement
HSTTV25-48-TL	HSTTV25-48-Q
HSTTV25-D10	No Replacement
HSTTV25-D2	No Replacement
HSTTV25-D6	No Replacement
HSTTV25-Q	HSTTV25-C
HSTTV38-Q	HSTTV38-C
HSTTV38-T2	No Replacement
HSTTV38-T4	No Replacement
HSTTV38-T6	No Replacement
HSTTV50-T4	No Replacement
HSTTV50-T6	No Replacement
HSTTV75-Q	HSTTV75-C
HSTTV75-T2	No Replacement
HSTTV75-T4	No Replacement
HSTTV75-T6	No Replacement
HSTTVVA100-48-40	HSTTVVA100-48-5